



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: September 19, 2006

Supervisor *[Signature]*

Mine Name: Low Down 1
Operator Name: Mike Dettamanti/Don Wood
P.O. Box 291
Kanab, Utah 84741

Permit number: S/025/019
Inspection Date: September 11, 2006
Time: 12:30 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Abandoned

Weather: Clear, warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspected the site while in the area to document the location and status of the site.

Directions to Site:

See GIS map in the file.

Inspection Summary:

The operator has not operated on this site since about 2002. This is due to the fact that the BLM declared the site forfeited due to non-payment of claim fees and the operator was no longer able to access the site.

Vegetation has begun to grow within the disturbance and on the access road.

Conclusions and Recommendations:

The Kanab FO has authorized the closure of this permit. A document will be prepared closing this permit.

Inspector's Signature

[Signature: Doug Jensen]

Date:


9/20/06

dj:pb

cc: Mike Dettamanti

Doug Powell, BLM, Kanab FO UTU-71335

O:\M025-Kane\S025019-LowDown\Inspections\09112006insp.doc



1 inch equals 2,000 feet